



Č.j.: KRPM-75078-2/ČJ-2026-141106 3 situace

SOUHLASÍ

Dne 2.6.2026

K. KUMAR
 KRAJSKÉ ŘEDITELSTVÍ POLICIE
 OLOMOUCKÉHO KRAJE
 DOPRAVNÍ INSPEKTORÁT
 790 01 JESENÍK, MORAVSKÁ 780/4



The diagram shows a road layout with two horizontal lines representing roads. A vertical line crosses both horizontal lines on the left side. On the right side, a triangular warning sign is placed on the top horizontal line, and another triangular warning sign is placed on the bottom horizontal line on the left side.

